Figure S1: The MAXAR image of Kolyma Route section before landslides caused to heavy rains in 2020 (a) and after in 2022 (b). Field observation of debris landslides (c) the souths aspect slope and (d) the north aspect slope.

4