Response Figures



Figure R1. (a) Photograph of the water spray test for the 45-degree H-Tube radiation shield inlet. The test is conducted for the stainless-steel version of H-Tube (H-Tube$_{SS}$) with SHT41 sensor installed inside the shield. (b) Close-up photograph of the H-Tube inlet after the water spray test.




Figure R2. Results of the water spray test without (a) and with (b) wire mesh cap.

Response Figures



Figure R3. Photograph of the cable outlet from the H-Tube to the power supply and data logger via a hole on the connector between the outer tube and the elbow. Note that the setup in the photograph is for SHT4x, but similar setup also used for HMP155.