Brief Communication: An Ice-Debris Avalanche in the Nupchu Valley, Kanchenjunga Conservation Area, Eastern Nepal

Alton C. Byers,[1] Marcelo Somos-Valenzuela,[2] Dan H. Shugar,[3] Daniel McGrath,[4] Mohan B. Chand,[5] Ram Avtar[6]

[1]Institute of Arctic and Alpine Research, University of Colorado at Boulder, Boulder, Colorado USA 80309
[2]Department of Forest Sciences, Faculty of Agriculture and Environmental Sciences, University of La Frontera, Temuco, Chile, 4780000
[3]Water, Sediment, Hazards, and Earth-surface Dynamics (waterSHED) Lab, Department of Geoscience, University of Calgary, 2500 University Drive NW, Calgary, Alberta, T2N 1N4
 Canada
[4]Department of Geosciences, Colorado State University, Fort Collins, CO, USA, 80523
[5]Department of Environmental Sciences, Patan Multiple Campus, Tribhuvan University, Lalitpur, Nepal
[6]Faculty of Environmental Earth Science, Hokkaido University, Sapporo Japan 060-0810

Correspondence: Alton C. Byers (alton.byers@colorado.edu)

Abstract Beginning in December 2020, a series of small-to-medium, torrent-like pulses commenced upon a historic debris cone located within the Nupchu valley, Kanchenjunga Conservation Area (KCA), Nepal. Sometime between 16 and 21 August 2022 a comparatively large ice-debris avalanche event occurred, covering an area of 0.6 km^2 with a total estimated volume of order 10^6 m^3. The area of the debris cone left by the August 2022 event increased the historic debris cone area by 0.2 km^2 (total area: 0.6 km^2). Although no human or livestock deaths occurred, the increase in torrent-like pulses of debris upon this historic debris cone since 2020 exemplifies a style of mass movement that may become increasingly common as air temperatures to rise in the region. Although the magnitude of this event was small compared to events like the 2021 Chamoli avalanche, the widespread distribution and frequency of comparable events presents a substantial, and potentially increasing, hazard across High Mountain Asia.

1 Introduction

Large magnitude but low frequency events in the high mountains can include a variety of familiar and poorly understood cryospheric processes, including glacial lake outburst floods (GLOFs) (Lamsal et al., 2014), snow/ice/rock avalanches (Shugar et al., 2021), landslide-induced avalanches and floods (Byers et al., 2019), englacial conduit floods (Rounce et al., 2017), and others (see: Byers et al. 2022). Today, enhanced communications and remote sensing technologies enable rapid identification and location of such events, often within hours of their occurrence. Many, however, remain unreported because of their remoteness, inaccessibility, poor communications, and/or absence of people (see: Byers et al., 2020). In this *Brief Communication,* we report on a large ice-debris avalanche that occurred sometime between 16 and 21 August 2022 in the Kanchenjunga Conservation Area (KCA), eastern Nepal. The event is noteworthy not only because of its probable linkages to climate change impacts in the region, but also because local residents were unaware of its occurrence, as were the Government of Nepal and climate change research entities in Kathmandu. Here we briefly document the event and describe its present and future implications for local communities, scientists, and governments.

Figure 1. Kanchenjunga Conservation Area and location of the Nupchu ice-debris avalanche.

2 Setting

The KCA is a 2,035 km^2 protected area established in 1997 by the Nepalese Department of National Parks and Wildlife Conservation, with management responsibility handed over to local communities in 2006 (WWF Nepal 2018) (Figure 1). It is home to a range of ethnic groups of primarily Tibeto-Burman origin that include Limbu, Rai, Tamang, Gurung, Magar, Chhetri, and Sherpa (Thapa, 2009). Livelihoods were traditionally based upon agriculture, livestock raising, and trade with Tibet, but globalization, outmigration, and new road construction over the past 15 years has rapidly changed the character of both the social and environmental landscape. The South Asian monsoon dominates weather patterns, with most rainfall falling between June and September (Kandel et al., 2019).

Based upon an analysis of 1962–2000 satellite imagery, valley and mountain glaciers in the KCA cover approximately 488 $\pm$ 29 km^2 and exhibit an overall negative glacier surface area loss of 0.5 $\pm$ 0.2% yr^{-1} (Racoviteanu et al., 2015). Valley glaciers are largely debris-covered and have been receding since the most recent maximum during the Little Ice Age. Hooker (1854), for example, wrote in 1849 of observing glacial moraines that provided proof "…of glaciers having once descended to from 8,000 to 10,000 feet in every Sikkim and east Nepal valley…" (Hooker, 1854: 166). The British alpinist Freshfield (1903: 236) writes of the "glacial shrinkage" he encountered in the Lhonak region in 1899, as well as

69 throughout both the Nepal and Sikkim sides of the Kanchenjunga massif. Although the Kanchenjunga
70 region received some of the earliest study, exploration, and mountaineering expeditions in Nepal by
71 outsiders (Thapa 2009), relatively little glacier and cryospheric hazards research has been conducted
72 to date. For example, until 2019 only one GLOF event was on record for the region (Watanabe et al.,
73 1998; ICIMOD, 2011), although subsequent research revealed that at least seven others had occurred
74 since 1921 (Byers et al., 2020). The Nupchu valley, where the ice-debris avalanche of concern
75 occurred, is used seasonally for yak herding, potato farming, and tourism, with four operational tourist
76 lodges in the village of Kampuchen as of the fall of 2022 (Figure 1).

77 **3 Methods**
78
79 Field-based observations and assessments of Nupchu Pokhari (glacial lake), other nearby lakes, and
80 the ice-debris avalanche were conducted between 1−20 September 2022. Methods included GPS-
81 based route mapping, photography of avalanche features, oral testimony, and literature reviews. A
82 Nikon Forestry Pro Rangefinder was used to measure the depth of ice/debris deposits where the
83 Nupchu river had incised deposits down to the original streambed. Historic (declassified KH-9 Hexagon
84 satellite imagery; see: Maurer et al., 2019; Dehecq et al., 2020) and recent (Planet Dove and
85 SuperDove) satellite imagery revealed the sequence of avalanche/debris flow events between 1975
86 and 2023 (Figure 2). Numerical simulations of the avalanche were conducted using R.Avaflow version
87 3 (Mergili and Pudasaini, 2014−2023; Mergili et al., 2017), a state of the art software that has been
88 used globally to study ice/rock avalanches events (Zhang 2022). Numerical simulations were used to
89 provide upper limit volume estimation of the avalanche, which were constrained by field observations.
90 We used the parameters from Zhang et al. (2022) to produce a single-phase model scenario for three
91 different volumes: 1, 2.5, and 5 million m^3. For calibration, we modified the internal friction angle of
92 the mixture to match the extension of the debris left by event. For the terrain elevation, an ALOS
93 PALSAR Radiometric Terrain Corrected high-resolution 12.5 m DEM was used
94 (AP_13152_FBD_F0540_RT1) (ASF DAAC, 2014).

95 **4 The Event**

96 The investigation of the Nupchu valley was initiated by local concerns about Nupchu Pokhari
97 (27.790708° N, 87.934275° E) as being one of the most dangerous glacial lakes in terms of a potential
98 GLOF (Figure 1). Periodic, smaller floods from the upper Nupchu valley were reported, and assumed
99 locally to have originated in the Nupchu Pokhari, although no supporting evidence was available. Our
100 field reconnaissance results of Nupchu Pokhari on 12 September 2022, however, suggested that the
101 lake posed a moderate risk of flooding, largely based on the absence of overhanging ice and other
102 potential flood triggers. This assessment corroborates the findings of Rounce et al. (2017) which
103 concluded that the 0.129 km^2 Nupchu Pokhari presented only a moderate risk of flooding because of
104 (a) no apparent growth between 2000 and 2015, (b) absence of avalanche pathways into the lake (i.e.,
105 in line with the direction of the lake and its outflow), and (c) absence of landslide pathways entering
106 the lake.

107 The August 2022 ice/debris avalanche event was unexpected. Field staff had conducted a
108 reconnaissance of the valley below Nupchu Pokhari in early August 2022 to check out potential
109 camping sites, at which time the upper valley was primarily pastureland. When the field team and A.C.
110 Byers returned in early September, the original path was blocked by massive ice-debris avalanche
111 material (27.774328° N, 87.941064° E) that had clearly occurred at some point in the interim (Figure

112   2). Our team and *dzopkio* (yak-cattle crossbreeds used as pack animals) were nevertheless able to
113   climb up and over the avalanche debris to the upper Nupchu valley, but at the time the source and
114   triggers related to the event remained unknown.

115   The original historic debris cone was found to have covered an area 0.402 km^2 that had been relatively
116   stable for at least 45 years, based upon the oldest satellite imagery available (i.e., 1975) (Dehecq et al.,
117   2020) (Panel A, Figure 2). Time series satellite images revealed the periodic occurrence of surficial
118   debris flows upon this original deposition. That is, beginning in 2020, a series of small-to-medium,
119   torrent-like pulses commenced (Panel C through G, Figure 2), culminating in the relatively large event
120   that occurred sometime between 16 and 21 August 2022 (Panel H, Figure 2). The area of the debris
121   cone left by the August 2022 event increased the original area covered by 0.2 km^2 (total area: 0.6
122   km^2). Of the three different volume estimates tested (1, 2.5, and 5 million m^3) using R.Avaflow, an
123   avalanche volume of 1×10^6 m^3 most consistently matched the extent (red line) and depth of the new
124   debris cone deposited as determined by our field observations (Figure 3).

125
126   Our team was unable to locate the event on any seismographs, most likely related to the absence of
127   instrumentation in this part of the eastern Himalayas. Based upon direct field observations as well as
128   satellite imagery, the avalanche had clearly blocked and temporarily dammed the water from the
129   Nupchu Khola (river) at its onset, which was nevertheless able to cut down through the ice and
130   sediment deposited to form a steep canyon estimated at >10 m depth. The presence of shrubs (e.g., *J.*
131   *indica*) fully stripped of their bark was testimony to the high velocities of the flood- and meltwater
132   produced by frictional forces during the event, a phenomenon reported for other rockfall-induced
133   landslides in Nepal (Byers et al., 2019).

134
135   **5 Discussion**

136
137   Interestingly, individuals in the community of Kampuchen, only 5 km downstream of the event, were
138   unaware of the avalanche. Yak herds had already returned from the high pastures to the village by
139   early August, the community was busy harvesting potatoes and preparing for the fall tourist season,
140   and no obvious changes in the Nupchu Khola had been observed (e.g., Kargel, 2014 for a description of
141   changes in the Seti Kosi prior to the catastrophic flooding of 5 May 2012). Thus, authorities in
142   Taplejung and Kathmandu were also unaware of the event as of September 2022, which is typical of
143   many large-scale cryospheric events in remote regions of the Himalayas (e.g., Byers et al., 2022).

144
145   Still, the acceleration of torrent-like pulses of debris upon the historic debris cone since 2020 suggests
146   that these events may be linked to contemporary warming trends, similar to those that may have
147   triggered larger-scale mass wasting events elsewhere in the Himalaya (e.g., Shugar et al.,
148   2021; Kääb et al., 2021; Taylor et al., 2023). The frequency of such ice-debris flow events within the
149   KCA region, and more broadly across the Himalaya, is unknown. However, with projections of
150   continued warming in these regions (e.g., Lalande et al. 2021), a more systematic approach to
151   determining their historic frequency, as well as a better understanding of their triggers, is warranted.
152   After further evaluation, vulnerable villages, such as Kampuchen, may wish to consider the installation
153   of preventative floodwater diversion mechanisms, such as the rock-filled gabion walls currently
154   protecting tourist lodges in the Mt. Everest region (e.g., Rounce et al., 2017; Byers et al., 2022) using
155   participatory processes as outlined in Watanabe et al. (2016).

Figure 2. A time series of satellite images showing the periodic occurrence of surficial debris flows upon the original deposition. These appear to have accelerated in both frequency in magnitude beginning several years ago, leading up to the main event that occurred between 16 and 21 August 2022. Blue dashed outline in panel H is the 1975 outline of the debris cone, while the dashed black circle identifies the failure zone. The photograph at the bottom provides an oblique view of the ice/debris avalanche about three weeks after it occurred (photograph by A. Byers). Panel H shows an image from early 2023, as imagery from immediately after the ice-avalanche in mid-August 2022 were partially obscured by clouds (KH-9 imagery courtesy of USGS; Planet Dove and SuperDove imagery courtesy of Planet Lab PBC).

Figure 3. Surface elevation change modeled with R.Avaflow for three different avalanche volumes: 1 x10⁶ m³ (top), 2.5 x10⁶ m³ (bottom left) and 5 x10⁶ m³ (bottom right). Of the three estimates, 1 x 10⁶ m³ most consistently matched the extent and depth of the new debris cone deposited in August 2022 (red line; the yellow line represents the extent of the historic debris cone).

5 Conclusion

Beginning in 2020, a series of small-to-medium, torrent-like pulses commenced upon a historic debris cone located approximately 2 km down valley from the lake, culminating in a relatively large avalanche event that occurred sometime between 16 and 21 August 2022. The August 2022 event deposited debris with an area of 0.6 km² and estimated volume in the order of 10⁶ m³. No fatalities from the event occurred because of the absence of humans and livestock in the vicinity when the event occurred. Likewise, no impoundment of the Nupchu Khola, and formation of a potentially dangerous backwater lake, occurred as a result of debris blockage, although such scenarios happen routinely in high mountain environments.

The improvement of remote area event reporting mechanisms, especially to authorities in the capital, Kathmandu, could help with the development of hazard mitigation technologies and response. Likewise, more systematic monitoring of cryospheric events by scientists, using remote sensing platforms and hazard mapping tools, could help with the development of more effective early warning systems for vulnerable communities, livestock, and adventure tourists. Ultimately, this could lead to a minimization of losses and damage due to multi-hazard events.

Data availability. Declassified KH-9 Hexagon satellite imagery is available at https://earthexplorer.usgs.gov/. Planet Dove and SuperDove satellite imagery is available at https://www.planet.com/explorer/. The ALOS PALSAR Radiometric Terrain Corrected high-res DEM"AP_13152_FBD_F0540_RT1" used for the R.Avaflow is available at https://search.asf.alaska.edu/.

Author contributions. ACB conceived the study and wrote the original narrative, with contributions from MS-V, DS, DM, MBC, and RA. MBC created Figure 1, DS and RA created Figure 2, and MS-V created Figure 3. MS-V conducted the numerical simulations of avalanche volumes shown in Figure 3. All authors revised and contributed to the final manuscript.

Competing Interests. The contact author has declared that none of the authors has any competing interests.

Acknowledgements. The Fulbright Nepal Scholar Program is thanked for its support of A.C. Byers during his six-month field study of contemporary impacts on alpine ecosystems in the Kanchenjunga Conservation Area, eastern Nepal. The Department of National Parks and Wildlife Conservation, Kanchenjunga Conservation Area, Department of Geography at Tribhuvan University are also thanked for their interest in and support of the project. Support for M. Somos-Valenzuela during the preparation of this paper was provided by the Chilean Science Council (ANID) through the Program of International Cooperation (PII-180008). Support for D.H. Shugar was provided by the Natural Sciences and Engineering Research Council of Canada (DG-2020-04207) and Alberta Innovates. Support for D. McGrath was provided by NASA award 80NSSC20K1343.

References

ASF DAAC, ALOS PALSAR Radiometric Terrain Corrected high res; Includes Material © JAXA/METI 2008 Accessed through https://search.asf.alaska.edu/on 11 February 2023. https://doi.org/10.5067/ 10.5067/Z97HFCNKR6VA, 2014.

Byers, A.C., Shugar, D., Chand, M., Portocarrero, C., Shrestha, M., Rounce, D., and Watanabe, T.: Three recent and lesser-known glacier-related flood mechanisms in high mountain environments, Mountain Research and Development, 42(2):A12-A22, https://doi.org/10.1659/MRD-JOURNAL-D-21-00045.1, 2022.

Byers, A.C., Chand, M.B., Lala, J., Shrestha, M., Byers, E.A., and Watanabe, T.: Reconstructing the history of glacial lake outburst floods (GLOF) in the Kanchenjunga Conservation Area, east Nepal: an interdisciplinary approach, Sustainability, *12*, 5407, https://www.mdpi.com/2071-1050/12/13/5407, 2020.

230

231 Byers, A.C., Rounce, D.R., Shugar, D.H. and Regmi, D.: A rockfall-induced glacial lake outburst flood,
232   upper Barun valley, Nepal, Landslides, 16, 533-549, https://doi.org/10.1007/s10346-018-1079-9,
233   2019.
234

235 Dehecq, A., Gardner, A.S., Alexandrov, O., McMichael, S., Hugonnet, R., Shean, D., and Marty, M.:
236   Automated processing of declassified KH-9 Hexagon satellite images for global elevation change
237   analysis since the 1970s, Frontiers Earth Science, 8, https://doi.org/10.3389/feart.2020.566802,
238   2020.
239

240 Freshfield, D.W.: Round Kangchenjunga: A Narrative of Mountain Travel and Exploration (historic
241   reprInt), 1903. www.forgottenbooks.com
242

243 Hooker, J.D.: Himalayan Journals Vol. 1, 1854, Orlando: The Perfect Library (historic reprint).
244

245 ICIMOD: Glacial lakes and glacial lake outburst floods in Nepal. Kathmandu: International Centre for
246   Integrated Mountain Development (ICIMOD), 109 pp, 2011.
247

248 Kääb, A., Jacquemart, M. n., Gilbert, A., Leinss, S., Girod, L., Huggel, C., Falaschi, D., Ugalde, F.,
249   Petrakov, D., Chernomorets, S., Dokukin, M., Paul, F., Gascoin, S., Berthier, E. and Kargel, J.: Sudden
250   large-volume detachments of low-angle mountain glaciers: more frequent than thought?,
251   Cryosphere 15(4), 1751–1785, https://doi:10.5194/tc-15-1751-2021, 2021.
252

253 Kandel, P., Chettri, N., Chaudhary, R.P., Badola, H.M., Gaira, K.S., Wangchuk, S., Bidha, N., Uprety, Y.,
254   Sharma, E.: Plant Diversity of the Kangchenjunga Landscape, Eastern Himalayas. Plant Diversity,
255   41(3), 153-165, https://doi.org/10.1016/j.pld.2019.04.006, 2019.
256

257 Kargel J.: One scientist's search for the causes of the deadly Seti River flash flood. Earth Observatory,
258   24 January, 2014.
259   https://earthobservatory.nasa.gov/blogs/fromthefield/2014/01/24/setiriverclues/; accessed on 15
260   December 2022.
261

262 Lalande, M., Ménégoz, M., Krinner, G., Naegeli, K., and Wunderle, S.: Climate change in the High
263   Mountain Asia in CMIP6, Earth Syst. Dynam., 12, 1061–1098, https://doi.org/10.5194/esd-12-1061-
264   2021, 2021.
265

266 Maurer, J.M., Schaeffer, J.M., Rupper, S., and Corley, A.: Acceleration of ice loss across the Himalayas
267   over the past 40 years, Science Advances, 5(6), https://doi: 10.1126/sciadv.aav7266, 2019.
268

269 Mergili, M., Fischer, J. T., Krenn, J. y Pudasaini, S. P.: R.avaflow v1, an advanced open-source
270   computational framework for the propagation and interaction of two-phase mass flows, Geosci.
271   Model Dev., 10(2), 553–569, https://doi:10.5194/gmd-10-553-2017, 2017.
272

273 Mergili, M. and Pudasaini, S.P., 2014-2023. r.avaflow - The Mass Flow Simulation Tool.
274   https://www.avaflow.org
275

276 Racoviteanu, A.E., Arnaud, Y., Williams, M.W., and Manley, W.F.: Spatial patterns in glacier
277   characteristics and area changes from 1962 to 2006 in the Kanchenjunga–Sikkim area, eastern
278   Himalaya, The Cryosphere, 9, 505–523, doi:10.5194/tc-9-505-2015, 2015.
279
280 Rounce, D., Byers, A. C., Byers, E. A., and McKinney, D. C.: Brief communications: observations of a
281   glacier outburst flood from Lhotse glacier, Everest area, Nepal, *The Cryosphere, 11, 443-449,*
282   doi:10.5194/tc-11-443-2017, 2017.
283
284 Taylor, C., Robinson, T.R., Dunning, S., Carr, R. and Westoby, M.: Glacial lake outburst floods threaten
285   millions globally, Nature Communications 14, 487, https://doi.org/10.1038/s41467-023-36033-x,
286   2023.
287
288 Thapa, R: Kanchenjunga: The Unique Gift of Nature. Kathmandu: Kanchan Printing Press, published by
289   Phupu Chowang Sherpa, 2009.
290
291 Watanabe, T., Khanal, N.R., and Gautam, M.P.: The Nangama glacial lake outburst flood occurred on
292   23 June 1980 in the Kanchenjunga area, eastern Nepal, Ann. Hokkaido Geogr. Soc., *72*, 13–20,
293   doi:10.14917/hgs1959.1998.13, 1998.
294
295 Watanabe, T., A. C. Byers, M, A. Somos-Valenzuela and D. C. McKinney: The need for community
296   involvement in glacial lake field research: the case of Imja Glacial Lake, Khumbu, Nepal Himalaya.
297   Chapter 13. In: Singh, R. B., Schickhoff, U., and Mal, S. (eds.): *Climate Change, Glacier Response, and*
298   *Vegetation Dynamics in the Himalaya: Contributions Toward Future Earth Initiatives*, Springer
299   International Publishing Switzerland, pp. 235-250, doi:10.1007/978-3-319-28977-9_13, 2016.
300
301 Zhang, T., Wang, W., Shen, Z., Zhan, N., Wang, Z. and An, B.: Understanding the 2004 glacier
302   detachment in the Amney Machen Mountains, northeastern Tibetan Plateau, via multi-phase
303   modeling, Landslides, https://doi:10.1007/s10346-022-01989-2, 2022.